HSS compliance – roof issues and moisture

Larry Russen
Chartered Building Surveyor

2025

1

Contents

- Introduction
- HSS1 and HSS 2 requirements
- Some other benchmark standards
- Structural considerations in traditional roof structures
- Drones and camera poles
- Conclusions



Learning objectives

- Consider some of the possible changes in the RICS HSS regarding roofs and moisture;
- Understand some of the structural 'rules' that can be applied to roof timbers;
- Consider and practice how some of those rules can be used in the real world.

3

3

Group discussion

What sort of pitched roof issues do we typically find in a residential property in the UK and how do we assess them?

4


Group discussion


What sort of pitched roof issues do we typically find in a residential property in the UK and how do we assess them?


FEEDBACK

5

5







Appendix A: Benchmarking the levels of inspection

A3 Safety, access and restrictions to inspection


Energy efficiency initiatives have resulted in thick layers of thermal insulation in many roof spaces. It is usually not safe to move across this material as it conceals joist positions, water and drainage pipes, wiring and other fittings. This may restrict the extent of the inspection and the scope of the report. Consequently, this matter should be discussed with the client at the earliest stage, be included in the terms of engagement and included in the report. Flat roof structures are usually inaccessible, although some information can sometimes be seen or deduced (e.g. where an accessible roof space abuts an adjoining flat roof). Parts of other elements are often visible in roof spaces, e.g. gable or party walls, chimney breasts and services – these are usually reported under each element.


Tell the client up-front in the ToE about the current limitations to roof inspections in 80% of roof spaces





9

		Roofs internal						
	Level of Service	ce Parts usually inspected & minimum level of inspection						
Research destroys Research planting and a distribution of the service of the ser	General	Type and nature of parts, materials (e.g. timber, metal, concrete composite), construction form (e.g. pitched, flat, trussed, 'cut' roof, 'A' frame, panel), lateral restraint, bracing, underside of roof covering including underlay (usually reported in 'roofs external'), ventilation, insulation, storage and access alterations. The RICS member will carry out an inspection of any reasonably accessible roof space that is no more than three metres above floor level, using a ladder. See Section A6 of this appendix for flats, tenements and similar dwellings.						
		Flat roof structures are usually inaccessible, although some information can sometimes be seen or deduced (e.g. where an accessible roof space abuts an adjoining flat roof). Parts of other elements are often visible in roof spaces, e.g. gable or party walls, chimney breasts and services – these are usually recorded under each element.						
	Level 1	Visual inspection ('head and shoulders') from access hatch only. The RICS member will not remove secured access panels and/or lift insulation material, stored goods or other contents. Check moisture levels of accessible timbers. The RICS member will not usually enter any roof you at this Level.						
	Level 2	As Level 1, including entering the roof space, paying particular attention to vulnerable locations prone to deterioration and damage, or visibly affected by damp and deterioration. Check moisture levels of an identified small sample of timbers and the functionality of the roof frame. Thermal insulation and stored items are not moved or lifted at this level.						
	Level 3	As Level 2, including entering all reasonably accessible parts of the roof space, with attention paid to all parts including wall plates where safe to do so and/or applicable. Check dimensions of main parts as necessary (e.g. rafters, purlins, joists, principal trusses). Check moisture levels of an identified larger sample of timbers trian at Level 2. Corners of insulation should be lifted so its thickness and type (and the nature of the underlying ceiling) can be identified. A small number of lightweight possessions should be repositioned, if necessary, so a more thorough inspection can take place.						









The further north is the property and the taller it is, the stronger is the wind 7.2.8 Restraint Also see: Chapter 6. Adequate restraint shall be provided to support the structure, distribute roof loads and prevent wind uplift. Strapping shall be of adequate strength and durability, and fixed using appropriate fixings. Restraint straps, or a restraining form of gable ladder, should be used where required to provide stability to walls, and be installed in accordance with the design. Lateral restraint straps should be located: • for homes up to and including three storeys (two storeys in Scotland), at a maximum spacing of 2m Lateral restraint straps should be fixed to the roof structure by either: • fixing to solid noggings using a minimum of four 50mm x • fixing to longitudinal bracing members using eight 25mm

4mm steel screws or four 75mm x 4mm (8SWG) round nails, with one fixing in the third rafter (Figure 15), or

Good fixings, not plasterboard nails!

 roof cassette systems are used in forming room-in-roof and the length of the raised collar is over 2m and the floor to ceiling dimension below the ceiling is over 2.4m fixing to longitudinal bracing members using eight 25mm x 4mm steel screws evenly distributed along the length of the strap (Figure 16). Alternatively, 100mm x 25mm timber members, fixed over four trusses and nailed in accordance with Clause 7.2.9 can be used where the position of the strap does not coincide with a longitudinal binder.


15

This is current best **7.2.12** Access Also see: Clause 7.2.15 practice Roof voids shall be provided with suitable access. Access to roof voids should be provided to allow for periodic inspection, maintenance and removal of permanent equipment. Access should: be provided to the main roof space and to voids which include securely fixed boarded walkways between the contain permanent equipment (eg heating, water storage, opening and the permanent equipment and at each piece of permanent equipment, a minimum 1m2 platform should be energy producing and ventilation equipment, etc), service connection boxes or connection points for TV aerials, etc provided to facilitate maintenance permit the removal of permanent equipment located in the boarded walkways and working platforms should be roof space securely fixed with a minimum clearance of 50 mm between the top of the insulation and the underside of the walkway to have a minimum opening width of 520mm in each direction ensure a clear ventilation space. not be located directly over stairs or in other hazardous locations Access may not be required where a void does not contain any permanent equipment, service connection boxes or connection points for TV aerials, etc where: the main roof consists of only a small void below the ridge small voids are present in the eaves (including those which where the raised collar is less than 2m in length contain water pipes only).

Good insulation in the roof helps prevent excessive heat loss in winter and warming of habitable rooms such as bedrooms in the summer. However, the existing depth of the insulation in the roof means the timbers (called 'joists') that support the ceilings underneath have been covered. This can be a problem later when workpeople such as plumbers, electricians and roofers need to get into the roof space and get access to parts of the property that need repair or maintenance. Many work-people will refuse to get into such a roof for safety reasons. This means maintenance does not get done and can also mean emergency work may not get done as guickly as is required. This is particularly important in a property such as this, with smoke detectors, electrical installations and sometimes complicated plumbing and heating systems that can in part only be accessed through the roof. [amend or alter as required] I therefore recommend you consider installing a permanent access walkway fixed to the joists now / soon. [delete] The best position for such a walkway is usually under the highest part of the roof, i.e. the top of the roof (called the 'ridge') at least and sometimes more extensive access is required. In this property, more extensive access walkways are required due to the size and shape of the property. [delete and or alter as required]

17





eurocode 5 span tables for solid timber members in floors, ceilings and roofs for dwellings



TRADA Technology Ltd Chiltern House Stocking Lane Hughenden Valley High Wycombe Buckinghamshire HP14 4ND

tel: +44 (0)1494 569600 fax: +44 (0)1494 565487 email: information@trada.co.uk website: www.trada.co.uk 3 Design Considerations

Notches should be not deeper than the lesser of 0.125 times the depth of a joist or 35mm, and should not be cut closer to the support than 0.07 of the span, nor further away than 0.25 times the span. Each end of the joist may be edge notched at either the top edge or the bottom edge.

Holes should have a diameter not greater than 0.25 times the depth of a joist or 65mm, whichever is smaller, and should be drilled at the joist centreline. They should be not less than 3 diameters (centre to centre) apart and should be located between 0.25 and 0.4 times the span from the support.

Drilled holes and edge notches in the same beam that comply with the above paragraphs must be horizontally separated by at least 100mm of full section.

Notches or holes should not be cut in rafters, purlins or binders unless approved by the building designer

Rafters restrained by ceiling ties at eaves level may be birdsmouthed at supports to a depth not exceeding one third of the rafter depth.

Timber herringbone strutting should be at least 38 x 38mm but should not be used where the distance between joists is greater than 3 times their depth.

Solid blocking should be at least 38mm thick.

Strutting and blocking should extend at least three-quarters of the joist depth.

At each end of a row of strutting the outer joist should be blocked solidly at the perimeter wall.

The minimum bearing length at supports for ceiling joists should be 35mm and binders should be 60mm. However, it is normal for ceiling joists to run across at least the full width of the wallplate to accommodate the fixings between ceiling joist and rafters. Where longer bearing is required due to high bearing stresses, typically for larger sections, it is indicated to tables by shading.


Unless justified by specialist calculation, the minimum bearing length at supports should be 35mm for rafters and 80mm for purlins. However it may sometimes be necessary to provide longer bearing for


19

Weights (loads) of materials



- Plain clay tiles at 100mm gauge 77.00 kg/m²
- Single clay pantile at 315mm gauge 42 kg/m²
- Concrete tile double roman at 343mm gauge – 45 kg/m²
- Flat concrete tiles at 355mm gauge 51 kg/m²
- Best slate, 4mm thick 31.00 kg/m²
- Medium strong slate, 5mm thick 35.00 kg/m²






Propensity to suffer from wind – based on BRAD 'A'

- The higher the property is, the greater is the wind;
- Properties within 10k of the coast are subjected to more wind;
- Properties on slopes and in hilly locations are subjected to more wind ('roughness factor');
- Properties in 'town' locations suffer from less wind as compared with 'country' locations

23



3.6.4 Recording all reasonably available information

The RICS member or RICS-regulated firm **must** keep a record of the inspection of the property and local area (traditionally known as 'site notes') for as long as is legally required. The RICS member or RICS-regulated firm **must** ensure that the information is in a format to allow for subsequent reflection before and during preparation of the report for the client. See sections 3.1 and 3.7.

The amount of recorded information will depend on the Level of Service but **must** include all information relevant to the instruction. Examples include:

- any material information and other relevant information obtained from the vendor, occupier, agent, neighbours or others
- the form of construction and materials, condition, defects, deficiencies, personal hazards, risks to the property, legal issues, any other matter(s) where relevant to the Level of Service and circumstances of inspection (including any limitations)
- the nature, position and results of checks (e.g. moisture meter or spirit level readings) made to the fabric structure
 and other parts as necessary (e.g. building services) and what was found

 see Fryer v Bunney (1982) 2 EGLR 130
- appropriate dimensions (e.g. thickness of walls or timber sizes) and diagrams (e.g. a sketch of an elevation with damage and crack patterns), sketch plans (e.g. a plan of the site, or annotated floor plans) – also see section 5.3
- any images captured during the inspection –photographs and videos are helpful for reflection during preparation of the
 report but are supplementary to the process and must not be used as an alternative or a substitute for the physical
 inspection that the signatory of the report must carry out.

Level 2 Services on additional risk properties and all Level 3 Services will include more detailed assessments of the property when compared with a typical Level 2 Service for a conventional property – the amount of recorded information will therefore be greater.

25

Why we look for moisture - Fryer v Bunney [1982] 2 EGLR 130

- The defendant, in carrying out a building survey of a residential property, reported that it had been checked with a damp meter and that there was no evidence of damp. Soon after purchase, when the property was being redecorated, it was discovered that water was leaking from defective central heating pipes under the hall floor. The defendant was held negligent for not having made more use of the damp meter and thus discovering this dampness, which was not discoverable by sight or touch.
- Although the survey report indicated that a meter had been used, there were no records of any readings for parts of the house. It was shown that if sufficiently extensive readings been taken, the damp would have been shown;
- Newey J was sympathetic to the defendant surveyor, despite his finding of negligence: 'I am quite sure he did not deliberately decide to skimp his work. I am quite sure he did not say to himself that day: 'Well, I will save myself 10 minutes, a quarter of an hour or half an hour by not checking with the Protimeter the inside walls.' I am sure he did not do that. I think this is one of those cases of a man doing a job of a standard type perhaps too frequently.'

This case means all surveyors must record where they take readings and what the results are

Why and how we look for moisture

- 'Framework that can be used for moisture investigations in buildings of all ages and types' – pp 3;
- 'assumes that a non-invasive inspection will be undertaken initially' – pp 3;
- 'only suggest remedial works that are proportionate to to any defects discovered and respect the nature of the property' – pp 3;
- build a holistic picture of the building...including...construction date...materials and techniques...setting elevation, wind exposure, flooding etc.)...alterations...use...condition' – pp 5 – 6;
- 'Understand the differences between modern and traditional construction' – pp 6;



27

Why and how we look for moisture

- 'traditional building fabrics may be subject to seasonal fluctuations/cycles' – pp 9;
- 'Understand the reasons for surface mould and condensation in buildings' – pp 11;
- 'Understand the significance of salts in assessing moisture problems...how such salts can damage building materials' – pp 11;
- 'Be able to conduct a thorough inspection...to enable assessment of its condition...including above- and belowground water supply services' – pp 12;
- 'Provide a holistic diagnosis that identifies and deals with causes, rather than focusing on symptoms...dealing with damp is often a staged process...obvious defects first...period for monitoring...reassess before moving on to other treatments' pp 13;
- 'remedial works...must be proportionate to the defect and significance of the building' – pp 13.





How accurate are 'moisture' meters?

In relation to measuring these moisture levels in buildings, the main problem facing residential practitioners is that moisture meters cannot accurately measure the moisture content of all building materials. As a consequence, manufacturers calibrate their meters to measure the moisture content of one material only – timber. This is because timber is a reasonably consistent material and the probes of a conductivity meter can usually be pushed by a few millimetres below the surface into the timber itself. A number of leading commentators agree that the readings give a reasonably accurate measure of the actual moisture content in that timber component in percentage terms. However, Ridout and McCaig (2016) found that conductivity meters are only accurate at lower moisture contents. His research revealed that for moisture contents in excess of 22%, the accuracy of moisture meters 'diminishes considerably'.


The Timber Research and Development Association also confirmed this view. They stated that when used in timber, most of the moisture meter readings will be within plus or minus 2% of the true moisture content within the range of 8 and 25%. Outside of this range, TRADA says the readings should be viewed as indicative only (TRADA 1999). This will be discussed again in the chapter on wood rotting fungi

29


So what does this mean for the residential practitioner? Here are our recommendations for conductivity moisture meters:

- For timber components Where you are able to press the pins of the meter a few millimetres into the timber, the percentage values shown on the LED are likely to be close to the actual moisture content of the timber. However, where moisture levels are higher (say 24–26% and more), the accuracy of the meter is likely to reduce, so use these values with care;
- **For all other building materials** Even if you are able to press the pins of the meter below the surface of the material, the figures shown will bear no relation to the actual moisture content. In these cases, record the colour of the LED lights on the read-out panel in your site notes.


In both cases, the information provided by a moisture meter does **NOT** provide you with a diagnosis of the moisture problem. Instead, the readings can provide you with useful data that can be combined with other information to enable you to come to a more balanced judgement. In many circumstances, higher moisture meter readings will be the start of the 'following the trail' process.




Dead load in kN / m², Snow load in this column for loads 3rd edition kN/m^2 $50 - 75 \text{ kg} / \text{m}^2$ Table 6.17 Permissible clear spans for single-span common or jack rafters Slope of roof 30.0° or more but less than 45.0° Imposed load $q_{
m k}$ = 0.60 kN/m or $Q_{
m k}$ = 0.90 kN Strength Class C16 Service Class 1 or 2 Dead loads $g_{\rm k}$ (kN/m²) excluding self-weight of rafter $g_{
m k}$ not more than 0.75 g_k not more than 0.5 k not more than 1.00 Spacing of rafters (mm) Size of rafter Breadth Depth 450 600 400 450 (mm) Maximum clear span (m) 100 1.83 1.61 1.61 1.52 2.29 2.17 2.12 1 99 38 125 2 45 2.40 2 29 224 2 12 38 150 3.08 3.02 2.87 2.87 2.80 2.64 2.71 2.47 2.64 3.82 3 57 3.57 3.33 195 4 24 4.15 3 92 3 92 eurocode 5 span tables 100 1.95 1.92 1.84 1.84 1.81 1.72 1.72 1.62 for solid timber members in floors, ceilings and roofs for dwellings 2.61 2.56 2.44 2.44 2.39 2.26 2.26 2.12 150 3.28 3.21 3.05 3.05 2.98 2.80 2.80 2.62 195 4.49 4.39 4.14 4.14 4.04 3.78 3.89 3.78 3.52 47 100 2.01 1.98 1.90 1.90 1.86 1.81 1.77 1.67 125 2.68 2.63 2.51 2.51 2.46 2.32 2.38 2.32 2.18 47 3.37 3.30 3.13 3.06 2.87 2.95 2.87 2.69 150 3.13 4.61 4.51 4.25 4.25 4.14 3.88 3.99 3.88 3.61 ALS/CLS 1.83 1.73 1.69 1.61 1.52 1.73 1.61 2.77 2.43 2.28 3.87 3.44 3.12 3.66 Nominal bearing of 35mm to be doubled - See



4th ed	ition		s is the clas		J			dead lo 3 x 184r		
Eurocoo	de 5 span	tables for s	olid timbe	r membe	rs			safely s		
		To management		-	THE PARTY	CHARLES THE R	DESCRIPTION.		THE PERSON	O'S A LOCK
Table 6	17 Parmis	sible clear	enane fo	r single-s	nan com	mon or iac	k rafters		7.7	
		more but less							This t	able uses
Strength C	_		Class 1 or		1000 4k - 0.	oo kiem or g	, - 0.50 A	"	target	t (=sawn)
C16	6	Dead loads	g _k (kN/m²)	excluding :	self-weight o					
011	<u> </u>	g _k not more			g _k not mo	re than 0.75		g _k not mo	ore than 1.00	0
Size of ra		Spacing of				•••				
Breadth (mm)	Depth (mm)	400	450	600	400	450	600	400	450	600
(iiiii)	(111111)	Maximum c	lear span (m)				_		
38	100	1.83	1.81	1.73	1,73	1.70	1.62	1.65	1.62	1.5
38	125	2.45	2.41	2.30	2.30	2.25	2.13	2.18	2.13	2.0
38	150	3.09	3.03	2.88	2.88	2.81	2.65	2.72	2.65	2.4
38	195	4.25	4.16	3.93	3.93	3.83	3.58	3.68	3.58	3.3
44	100	1.96	1.93	1.85	1.85	1.82	1.73	1.76	1.73	1.6
44	125	2.62	2.57	2.45	2.45	2.40	2.26	2.32	2.26	2.1
44	150	3.28	3.22	3.06	3.06	2.98	2.81	2.88	2.81	2.6
44	195	4.50	4.40	4.15	4.15	4.05	3.79	3.90	3.79	3.5
47	100	2.02	1.99	1.91	1.91	1.87	1.78	1.81	1.78	1.6
47	125	2.69	2.64	2.52	2.52	2.46	2.33	2.38	2.33	2.1
47	150	3.37	3.31	3.14	3.14	3.06	2.88	2.96	2.88	2.7
47	195	4.62	4.51	4.26	4.26	4.15	3.89	4.00	3.89	3.63
ALS/CLS	-								3100	
38	114	2.18	2.14	2.05	2.05	2.01	1.90	1.95	1.90	1.79
38	140	2.83	2.78	2.65	2.65	2.59	2.44	2.50	2.44	2.2
38	184	3.97	3.88	3.67	3.67	3.58	3.35	3.45	3.35	3.1





































	A2 General approach	() RICS
Level of Service	General description of Level of Service inspection practice	Harten parvey stands to which the stands
Level 1	Visual inspection only unless otherwise stated, inspecting all reasonably accessible elements but without any exposure of any part(s). However, unsecured doors and access hatches will be opened, e.g. into all rooms, roof spaces, eaves voids and similar.	2026 edition
	Inspection is carried out from ground level only and/or other readily and safely accessible positions, e.g. from windows or balconies.	
Level 2	As for Level 1 but with an enhanced visual inspection as above, with some checking.	
	At this Level, RICS members should at least use binoculars or similar equipment, e.g. a camera with zoom where this is reasonably necessary.	
Level 3	As for Level 2 with a more detailed visual inspection, examining each element in greater detail and to the fullest extent reasonably possible on the day of inspection, and with more extensive checking.	
	At this Level, RICS members should use equipment appropriate for the property type and circumstances.	

For some properties, especially additional risk properties, the RICS member or RICS-regulated firm could consider the advantages of using appropriate additional service equipment (e.g. a camera pole, drone, air flow meter, etc.) to further enhance their inspection of an element(s), weather and other restrictions permitting. This requirement will usually be clear or obvious from freely accessible information at the time of taking instructions and agreeing the terms of engagement with the client.

51

Conclusions

- Read HSS 2 when it comes out;
- Use the benchmarks of good practice, e.g. those in the BRADs, NHBC Standards and TRADA (they're usually based on BSI or European or international Codes of practice);
- Have a documented and recorded system based on those benchmarks so you can consider and reflect on the movement and distortion;
- Judges like a system it demonstrates professional reflection;
 and
- Use a 'moisture meter' with care and report accordingly!

